

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name OFFICER BARNUM, DEVON	Case Number 24005939	Date of Crash 06/19/2024	Time 03:38 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence At the Intersection of W 105TH ST And PENN AVE S		City Bloomington	County HENNEPIN	

UNIT 1	Person Type DRIVER	Name (Last,First,Mi) WEIHER, SHANNON, ELIZABETH	Address (Street, City, State, Zip) 9126 FOX RUN CIR, EDEN PRAIRIE, MN 553472025	
	DOB 2/23/1974	Sex F	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	
	Passenger Name WEIHER, COLIN, PATRICK	Passenger Injury NO APPARENT INJURY	Passenger DOB 2/11/2008	
	Passenger Safety Equipment LAP AND SHOULDER BELT USED	Transported	Passenger Age 16	

UNIT 2	Person Type DRIVER	Name (Last,First,Mi) MILLER, THEODORE, KAMINSKI	Address (Street, City, State, Zip) 7219 LANHAM LN, EDINA, MN 55439	
	DOB 5/20/2003	Sex M	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

On 06/19/2024 at approximately 1632 hours, I Officer Barnum was dispatched to a motor vehicle accident report located at the intersection of 105th St W. and Penn Ave S.

Upon arrival, I met with unit one who stated they were traveling south on Penn Ave S. in the middle of the intersection of 105th St W. when they were struck by unit two. Unit two had moderate damage to the left back driver side tire and quarter panel. The front airbags were deployed on unit ones vehicle. Unit one stated they were not injured and denied medical attention. Due to the damage, Unit one required to be towed.

At this time, I made contact with Unit two. Unit two stated they were traveling from east to west on 105th St W. when they struck vehicle two in the middle of the intersection located at 105th St W, and Penn Ave S. During this impact, unit two's vehicle accrued moderate damage to the front end that in return set off the front airbags. The front bumper and hood were damaged during the impact. Due to this impact, Unit two required to be towed. Unit two stated that they were not injured and their passenger was also not injured. Both the driver and passenger denied medical attention.

Both unit one and unit two did not take responsibility for the accident. Both unit's stated that due to the intersection being uncontrolled by traffic control signs, the accident was mutual. Both unit's knew each other and swapped insurance without incident.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name PATROL SANDERS, MITCHELL	Case Number BP24006020	Date of Crash 06/21/2024	Time 05:30 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence OLD CEDAR AVE 100 FEET North From Its Intersection With OLD CEDAR AVE S		City Bloomington	County HENNEPIN	

UNIT 1	Person Type DRIVER	Name (Last,First,Mi) KOSLOSKE, CHERYL, CHRISTA	Address (Street, City, State, Zip) 7083 153RD ST W, APPLE VALLEY, MN 55124	
	DOB 8/15/1977	Sex F	Injury POSSIBLE INJURY (C)	Safety Equipment UNKNOWN
	Transported Not Transported	Alcohol Test Yes, Test Given	Alcohol Test Result .33 BAC	

Property Damage Information:

Agency/Organization	Property Description STREET LIGHT AND SHARP CURVE SIGN	Property Type PUBLIC	Yellow Tag #	Owned By: CITY
---------------------	---	-------------------------	--------------	-------------------

Witness Information:

Name WHITAKER, KATRINA CONSWELLA	Sex F
-------------------------------------	----------

Unit 1 was travelling NB on Old Cedar Ave S approaching a curve just south of the intersection of American Blvd E and Old Cedar Ave S. Unit 1 veered off the road striking the grass embankment. Unit one continued forward and struck a light pole which appeared to cause the majority of the damage to the vehicle as it was held in place by a concrete base. Unit one continued forward striking a street sign indicating a sharp left turn before stopping facing up hill north bound on the embankment.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name PATROL MURPHY, JACOB	Case Number 24006054	Date of Crash 06/22/2024	Time 02:37 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence -- NOT ON ROADWAY --		City Bloomington	County HENNEPIN	

UNIT 1	Person Type	Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DOB	Sex	Injury		Safety Equipment
	Transported	Alcohol Test		Alcohol Test Result	

UNIT 2	Person Type	Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DOB	Sex	Injury		Safety Equipment
	Transported	Alcohol Test		Alcohol Test Result	

Property Damage Information:

Property Owner Name HARDING, JENNIFER	Property Description PARKED VEHICLE	Property Type PRIVATE	DOB	Sex
--	--	--------------------------	-----	-----

Witness Information:

Name GYSLAND, NEAL ROBERT	Sex M
------------------------------	----------

On 06/22/2024 at 1437hrs I, Officer J. Hanson #318 responded to a Property Damage Hit and Run report at the Mall of America (8100 24th Ave S.) West Ramp level 2 Aisle E Row 2. The Reporting Party/Vehicle Owner Harding, Jennifer Ann DOB 01/06/1985 stated someone hit her 2010 Black Yukon with WI Plate AGM5091 while they were shopping inside the mall. I observed scuff marks and paint transfer to the rear driver-side quarter panel and rear bumper area of her vehicle. (Photos obtained and uploaded to AXON)

Harding stated a witness Gysland, Neal Robert DOB 08/09/1992 observed the crash happen. I made contact with Gysland who was parked next to Harding's vehicle. Gysland stated he observed a black Acura SUV attempt to park next to Harding's vehicle. The Acura cut the corner too narrow and struck Harding's vehicle on the rear driver-side and bumper area. The Acura then reversed back out of the parking space and drove away. Gysland stated the vehicle was driven by what appeared to be a black female. Gysland was able to take a photo of the suspect vehicle and the license plate which was an Alabama License Plate 2A0EHDA which came back on a 2008 Acura MDX to a Wallace, Christy Renee DOB 02/24/1979 out of Mobile, AL. (Photo uploaded to AXON)

Mall Security checked their Park Assist Cameras and advised the suspect vehicle was not on property. Mall Security checked the North lot and I checked the surface lots on mall property but was unable to locate the vehicle.

I was not able to locate any prior contacts involving the suspect vehicle or the owner (Wallace) in MN.

Harding was provided the BPD File Number and she advised she would give her insurance the suspect vehicle information to follow up.

End of report.
JH#318

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name OFFICER BURT, ANDREW	Case Number BP24006067	Date of Crash 06/22/2024	Time 08:01 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence At the Intersection of BUSH LAKE RD And W 106TH ST		City Bloomington	County HENNEPIN	

UNIT 1	Person Type DRIVER	Name (Last,First,Mi) MCGHEE, TAVIN, PATRICK	Address (Street, City, State, Zip) 1121 79TH AVE NE APT 3, SPRING LAKE PARK, MN 554322864	
	DOB 7/12/2000	Sex M	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	
	Passenger Name MOHAMED, NEIMA, ABDOURAZAK	Passenger Injury SUSPECTED MINOR INJURY (B)	Passenger DOB 11/11/1999	
	Passenger Safety Equipment LAP AND SHOULDER BELT USED	Transported Not Transported	Passenger Age 24	

UNIT 2	Person Type DRIVER	Name (Last,First,Mi) YUSUF, YAHYA, SHAMSADIN	Address (Street, City, State, Zip) 2247 HOLLOWAY AVE E, SAINT PAUL, MN 551093929	
	DOB 1/15/2003	Sex M	Injury POSSIBLE INJURY (C)	Safety Equipment LAP AND SHOULDER BELT USED
	Transported Not Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

Unit 1 was EB on 106th Street West and stopped at the intersection with Bush Lake Road. Traffic on Bush Lake Road does not have a stop sign. There are signs below the stop signs on 106th Street that advise cross traffic does not stop. Unit 1 entered the intersection eastbound as Unit 2 was southbound. Unit 2 struck the driver side of Unit 1.

Unit 1 driver said he did not see Unit 2 and also thought traffic on Bush Lake Road had a stop sign also.

The front seat passenger of Unit 1 complained of head and chest pain. The passenger was evaluated by Allina paramedics and declined transport. The driver of Unit 2 also had pain in his hand/wrist but was not transported.

Both vehicles were towed by Chiefs towing due to disabling damage/airbag deployment.

Unit 1 driver was cited for failure to yield to the right of way.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name MILLER, ANGELA	Case Number BP24006084	Date of Crash 06/23/2024	Time 09:45 <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM
Road of Occurrence At the Intersection of W DUPONT AVE And OLD SHAKOPEE RD		City Bloomington	County HENNEPIN	

UNIT 1	Person Type DRIVER	Name (Last,First,Mi) KOTZ, PAUL, EUGENE	Address (Street, City, State, Zip) 1354 ALAMEDA ST, SAINT PAUL, MN 551174116	
	DOB 9/2/1963	Sex M	Injury SUSPECTED MINOR INJURY (B)	Safety Equipment LAP AND SHOULDER BELT USED
	Transported Not Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

UNIT 2	Person Type DRIVER	Name (Last,First,Mi) HOGAN, PATRICK, CORNEILIUS	Address (Street, City, State, Zip) 16550 IRWIN CT, LAKEVILLE, MN 550444586	
	DOB 7/16/1964	Sex M	Injury SUSPECTED MINOR INJURY (B)	Safety Equipment LAP AND SHOULDER BELT USED
	Transported EMS Ground	Alcohol Test No, Test Not Given	Alcohol Test Result	

Witness Information:

Name ATKINS, ALYSSA RAE MARIELLE	Sex F
Name MOMON, PENNY NICHOLLE	Sex F

On 06/23/24 at approximately 0945 hours, Officers were dispatched to the intersection of 98th Street and Dupont Ave S for a rollover vehicle crash with one occupant trapped inside. When Officers arrived on scene there were two vehicles involved. Unit #2 was on the East side of Dupont Ave, facing South that was flipped and lying on the driver's side unknown damage or point of collision. Unit #1 was up on a hill in the grass, also on the East side of Dupont Ave facing Southeast with damage to the front of the vehicle. As the Fire Unit arrived on scene, Officers and bystanders were able to extract the driver from Unit #2 through the sunroof and placed in the grass to be checked out by Fire before the ambulance arrived.

Statement from Unit #1, driver was traveling South from the 35W exit ramp, through the intersection onto Dupont Ave. Unknown which direction Unit #2 was traveling from at this time. Unit #1 stated they had the green light at the intersection. This is where the collision occurred.

Statement from driver of Unit #2. Driver was traveling East on 98th Street through the intersection. Unit #2 stated he had the green light at the intersection. The two Units collided in the middle of the intersection. It appears that Unit #1 struck Unit #2 on the driver's side, causing it to spin and eventually roll and land on the driver side. Unit #1 went through the intersection, traveled up the hill and stopped just before colliding with a tree.

Both drivers sustained injuries. Unit #1 was checked out and did not go to the hospital with minor leg injuries. Unit #2 was transported to Ridges Hospital by Hennepin EMS for more severe injuries to his left side where he was struck. (Run #24051848).

Both Units stated to have had the green light at the intersection. Both Units were towed from the scene by Chief's towing.

Witness #2 was in front of Unit #1 at the stop light. She traveled South then turned left to travel East on 98th Street.

Witness #2 heard the loud brake screech and then saw Unit #2 rolling over in her rearview mirror. Witness #1 stated hearing the loud brake screech, saw the collision and the roll over. Both Witnesses were unsure which direction Unit #2 was traveling when the collision occurred and both unable to say which Unit had the green light.

Photos of the crash scene were taken and uploaded, both Units were provided a case number for insurance.