

Driver 1 was traveling westbound in the parking lot. Driver 2 was traveling eastbound in the parking lot. Near a slight curve in the road, both drivers collided with the front end of their vehicles. The vehicles ended up in the middle of the lanes, so it is not known if the vehicles were in their correct lane when the collision occurred.

Driver 1 said he was moving about 15 mph when he went around the corner. He did not have time to respond when he saw driver 2. Both vehicles drove into each other.

Driver 2 said he just got off of work and was heading to the apartment. He was on the right side of the road and was going approximately 35-40 mph. When he saw driver 1, he attempted to brake but the vehicle was slow to stop. He believes there are issues with the brakes.

Allina paramedics responded to the scene but both parties denied medical services. There were no apparent injuries.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency	Officer Name	Case Number	Date of Crash	Time
BLOOMINGTON POLICE DEPT	NYBECK, MATTHEW	25008315	09/09/2025	03:15 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence			City	County
At the Intersection of RIVERVIEW RD And RAMP372			Eden Prairie	HENNEPIN

UNIT 1

Person Type	Name (Last,First,Mi)		Address (Street, City, State, Zip)	
DRIVER	MATTESON, BRET, MATTHEW		354 98TH AVE NE, BLAINE, MN 554341352	
DOB	Sex	Injury	Safety Equipment	
8/1/1978	M	NO APPARENT INJURY	LAP AND SHOULDER BELT USED	
Transported	Alcohol Test		Alcohol Test Result	
	No, Test Not Given			

UNIT 2	Person Type	Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER	LOGAN, RICHARD, CHARLES		226 ARABIAN AVE W, SHAKOPEE, MN 553794643	
	DOB	Sex	Injury		Safety Equipment
	3/23/1981	M	NO APPARENT INJURY		LAP AND SHOULDER BELT USED
Transported	Alcohol Test		Alcohol Test Result		
	No, Test Not Given				

Two vehicle crash. No driver was injured. Veh #2 was towed. The front of veh #1 struck the driver's rear of veh #2.

Driver #1 stated: He was driving veh #1. He was in the left, left turn lane of W Old Shakopee Road to go southbound on 169. He was entering the intersection as he thought another vehicle was going to merge in front of him. He hit his brakes and hydroplaned. His vehicle struck veh #2.

Driver #2 stated: He was driving veh #2. He was in the right, left turn lane of W Old Shakopee Road to go southbound on 169. He was entering the intersection. He was struck by veh #1 and was spun around.

No further information.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency	Officer Name	Case Number	Date of Crash	Time
BLOOMINGTON POLICE DEPT	THUL, MEGAN	25008403	09/11/2025	04:47 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence	City	County		
W 90TH ST	Bloomington	HENNEPIN		

UNIT 1	Person Type	Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER	REIDLINGER, CRAIG, RONALD		4743 OAK CLIFF DR, EAGAN, MN 551223303	
	DOB	Sex	Injury	Safety Equipment	
	10/6/1960	M	NO APPARENT INJURY	LAP AND SHOULDER BELT USED	
Transported		Alcohol Test		Alcohol Test Result	
		No, Test Not Given			

UNIT 2

Person Type	Name (Last,First,Mi)		Address (Street, City, State, Zip)	
DRIVER	JOHNSON, JARON, ANTHONY		8811 BLAISDELL AVE S APT 9, BLOOMINGTON, MN 554202884	
DOB	Sex	Injury	Safety Equipment	
7/31/1996	M	NO APPARENT INJURY	LAP BELT ONLY USED	
Transported	Alcohol Test		Alcohol Test Result	
	No, Test Not Given			
Passenger Name		Passenger Injury		Passenger DOB
JOHNSON, ELIAS		NO APPARENT INJURY		1/11/2020
Passenger Safety Equipment		Transported		Passenger Age
CHILD RESTRAINT SYSTEM - FORWARD FACING				5
Passenger Name		Passenger Injury		Passenger DOB
JOHNSON, JUDAH		NO APPARENT INJURY		8/15/2025
Passenger Safety Equipment		Transported		Passenger Age
CHILD RESTRAINT TYPE UNKNOWN				0

Property Damage Information:

Property Owner Name URBAN LANDSCAPPING	Property Description GRASS	Property Type PRIVATE		
--	--------------------------------------	---------------------------------	--	--

V1 was waiting to exit from a private parking lot. D1 stated there was a school bus stopped in the right lane at a railroad tracks just to the East. D1 stated he did not see any other vehicles traveling Eastbound, so he pulled out into traffic. D1 did not see V2 traveling Westbound in the left lane, passing the bus, and struck V2.

No injuries reported on scene.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency	Officer Name	Case Number	Date of Crash	Time
BLOOMINGTON POLICE DEPT	BROWN, ERIKA	25008441	09/12/2025	01:04 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence	City	County		
At the Intersection of STEVENS AVE S And E 83RD ST	Bloomington	HENNEPIN		

UNIT 1	Person Type		Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER		TA, VU, QUOC		150 E 84TH ST, BLOOMINGTON, MN 554202314	
	DOB		Sex	Injury	Safety Equipment	
	2/13/1989		M	NO APPARENT INJURY	LAP AND SHOULDER BELT USED	
Transported			Alcohol Test		Alcohol Test Result	
			No, Test Not Given			

UNIT 2

Person Type	Name (Last,First,Mi)		Address (Street, City, State, Zip)	
DRIVER	ABDILLAHI, RODA, JAMA		67 W 77TH ST, RICHFIELD, MN 554234248	
DOB	Sex	Injury	Safety Equipment	
1/1/1969	F	NO APPARENT INJURY	LAP AND SHOULDER BELT USED	
Transported	Alcohol Test		Alcohol Test Result	
	No, Test Not Given			
Passenger Name		Passenger Injury		Passenger DOB
SMITH, ZANAYA, VIDA		NO APPARENT INJURY		10/5/2019
Passenger Safety Equipment		Transported		Passenger Age
NONE USED, MOTOR VEHICLE OCCUPANT				5
Passenger Name		Passenger Injury		Passenger DOB
RUSSELL, AARIZ, ABU		NO APPARENT INJURY		10/8/2018
Passenger Safety Equipment		Transported		Passenger Age
NONE USED, MOTOR VEHICLE OCCUPANT				6
Passenger Name		Passenger Injury		Passenger DOB
RUSSELL, AMIR, RASHAD		NO APPARENT INJURY		9/25/2012
Passenger Safety Equipment		Transported		Passenger Age
NONE USED, MOTOR VEHICLE OCCUPANT				12
Passenger Name		Passenger Injury		Passenger DOB
RUSSELL, AMINA, RAYANNE		NO APPARENT INJURY		2/17/2014
Passenger Safety Equipment		Transported		Passenger Age
NONE USED, MOTOR VEHICLE OCCUPANT				11

Witness Information:

Name	Sex
TA, VU QUOC	M

Driver of the car said he was driving south on Stevens Ave when he hit the rear driver side of a school bus in the intersection of 83rd St. He did not see the bus until he hit it as everything happened so fast. He believes he was going around 20 mph, and said the sun may have been causing a glare on his eyeglasses. When his car hit the bus, the bus dragged his car, causing it to spin in the middle of the intersection. He said he was wearing his seatbelt, however, his airbags did not deploy.

The driver of the bus said she was driving east on 83rd St when a car ran into the rear driver side of the bus. The bus had halfway cleared the intersection when the car ran into her. She said the car was moving really fast.

MN State Patrol CVI responded to the scene to complete an investigation.

An independent witness believes the bus was going too fast and over the speed limit.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency	Officer Name	Case Number	Date of Crash	Time
BLOOMINGTON POLICE DEPT	BROADHEAD, BAILEY	BP25008491	09/13/2025	08:02 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence	City	County		
At the Intersection of 24TH AVE S And E 82ND ST	Bloomington	HENNEPIN		

UNIT 1	Person Type DRIVER		Name (Last,First,Mi) HARRIS, MEDINAH, NADIA		Address (Street, City, State, Zip) 9120 OLD CEDAR AVE S APT 202, BLOOMINGTON, MN 554252355	
	DOB 12/7/1973		Sex F		Injury NO APPARENT INJURY	
					Safety Equipment LAP AND SHOULDER BELT USED	
	Transported		Alcohol Test No, Test Not Given		Alcohol Test Result	
	Passenger Name TURNER, JACOBY, MALIK		Passenger Injury NO APPARENT INJURY		Passenger DOB 2/2/2007	
Passenger Safety Equipment LAP AND SHOULDER BELT USED		Transported		Passenger Age 18		

UNIT 2	Person Type		Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER		PRICE, SUSAN, MARIE		500 54TH ST NW SITE 55, MINOT, ND 58703	
	DOB		Sex	Injury		Safety Equipment
	6/14/2003		F	POSSIBLE INJURY (C)		LAP AND SHOULDER BELT USED
	Transported		Alcohol Test		Alcohol Test Result	
	EMS Ground		No, Test Not Given			
	Passenger Name			Passenger Injury		Passenger DOB
	PRICE, ANN, MARIE			NO APPARENT INJURY		1/15/1981
	Passenger Safety Equipment			Transported		Passenger Age
	LAP AND SHOULDER BELT USED					44
Passenger Name			Passenger Injury		Passenger DOB	
PRICE, MARY, ELIZABETH			NO APPARENT INJURY		8/18/2011	
Passenger Safety Equipment			Transported		Passenger Age	
LAP AND SHOULDER BELT USED					14	

Vehicle 1 was traveling southbound on 24th Ave S from Lindau Lane. Vehicle 1 was traveling in the number 3 lane. While attempting to merge into the number 3 lane, Vehicle 1 did not ensure the lane was clear for a merge. Vehicle 1 struck vehicle 2 when attempting to merge. Vehicle 2 was traveling southbound on 24th Ave S from Lindau Lane in the number 2 lane. Vehicle 1's front driver side door struck the front passenger wheel well area of Vehicle 2.