

Bloomington Police Dept Incident Report
Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name OFFICER KOOSMANN, DENNIS	Case Number 25008755	Date of Crash 09/22/2025	Time 02:15 ☐ AM ☒ PM
Road of Occurrence At the Intersection of W 90TH ST And NEWTON AVE S			City Bloomington	County HENNEPIN

UNIT 1	Person Type	Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DOB	Sex	Injury		Safety Equipment
	Transported	Alcohol Test		Alcohol Test Result	

UNIT 2	Person Type	Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER	OSORIO HERNANDEZ, YENI, CRISTELA		2400 W 91ST ST APT 206, BLOOMINGTON, MN 554312162	
	DOB	Sex	Injury	Safety Equipment	
	12/17/1993	F	NO APPARENT INJURY	LAP AND SHOULDER BELT USED	
Transported	Alcohol Test		Alcohol Test Result		
	No, Test Not Given				

Hit and Run Crash.

Unit #1 is suspect vehicle. Occupied by 4 females. Driver was described as African 30-40 years old.

Unit #2 is victim vehicle. Driven by Osorio Hernandez.

Osorio contacted BPD to report the crash.

Osorio stated she was traveling east on 90th in the right lane when unit #1 moved from the left lane into her lane without a signal and the vehicles collided near Newton Avenue South.

Osorio and the other vehicle stopped.

Osorio took a photo of the other vehicle.

Osorio attempted to exchange info and the other vehicle drove off.

BPD Police Report also completed and forwarded to Investigations.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name OFFICER KOMENDANT, MARKO	Case Number BP25008783	Date of Crash 09/23/2025	Time 12:59 ☐ AM ☒ PM
Road of Occurrence -- NOT ON ROADWAY --			City Richfield	County HENNEPIN

UNIT 1	Person Type	Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER	LEBARON, KENNETH, JOSHUE		5350 W 140TH ST, SAVAGE, MN 553781968	
	DOB	Sex	Injury		Safety Equipment
	10/31/1991	M	NO APPARENT INJURY		NOT APPLICABLE
Transported	Alcohol Test		Alcohol Test Result		
	No, Test Not Given				

UNIT 2	Person Type		Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER		RONNING, REBECCA, RAE		5349 WOODLAWN BLVD, MINNEAPOLIS, MN 554171950	
	DOB		Sex	Injury	Safety Equipment	
	6/12/1955		F	NO APPARENT INJURY	NOT APPLICABLE	
Transported			Alcohol Test		Alcohol Test Result	
			No, Test Not Given			

Lebaron was in a fully marked police vehicle pulling into a parking spot. As he was pulling in he accidentally side swiped FCM318. Minor damage to the rear driver side bumper. No visible damage to the squad car.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name OFFICER KOOSMANN, DENNIS	Case Number 25008793	Date of Crash 09/23/2025	Time 04:27 ☐ AM ☒ PM
Road of Occurrence At the Intersection of W 84TH ST And NORMANDALE BLVD			City Bloomington	County HENNEPIN

UNIT 1	Person Type	Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER	BOTROS, SAMIR, ABDELMESSIH		2910 SCOTT AVE N, GOLDEN VALLEY, MN 554222742	
	DOB	Sex	Injury	Safety Equipment	
	8/10/1961	M	NO APPARENT INJURY	UNKNOWN	
Transported		Alcohol Test		Alcohol Test Result	
		No, Test Not Given			

UNIT 2	Person Type		Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER		SANDERS II, WILLIAM, REX		10205 TOLEDO CIR, BLOOMINGTON, MN 554372510	
	DOB		Sex		Injury	
	10/13/2005		M		SUSPECTED SERIOUS INJURY (A)	
				Safety Equipment		
				DOT COMPLIANT FULL FACE, UNKNOWN		
Transported		Alcohol Test		Alcohol Test Result		
EMS Ground		No, Test Not Given				

Witness Information:

Name	Sex
LAGRO, HENRY OLIVER	M

Passenger vehicle vs. motorcycle crash.

Unit #1 was stationary at a red light in the turn lane to go west onto 84th street.

Unit #2 was traveling north on Normandale in a straight lane, believed to be the far right / east lane.

Unit #1 turned right across three lanes of traffic pulling in front of unit #2 as he did so. Unit #1 was attempting to go onto east bound 84th street as he just got an Uber eats order that he was trying to fulfill.

Unit #2 ran into the side rear right passenger door of unit #1.

Unit #1 then pulled forward onto 84th street.

Unit #2 was injured and laid in the roadway after experiencing a severe impact into the side of unit #1.

Unit #2's driver was transported via Allina Ambulance to HCMC for care. He appeared to be unconscious when he left the scene.

The driver of unit #1 was arrested for Criminal Vehicular Operation / Great bodily injury.

Traffic Investigations took over the scene and case.

Bloomington Police Dept Incident Report
Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name OFFICER MULVIHILL, TRISTEN	Case Number BP25008828	Date of Crash 09/24/2025	Time 08:15 ☐ AM ☒ PM
Road of Occurrence At the Intersection of PENN AVE S And 81ST ST W		City Bloomington	County HENNEPIN	

UNIT 1	Person Type DRIVER	Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DOB	Sex F	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED	
	Transported	Alcohol Test No, Test Not Given		Alcohol Test Result	
	Passenger Name ALI, ABDULAH, MOHAMUD		Passenger Injury NO APPARENT INJURY		Passenger DOB 10/28/2007
	Passenger Safety Equipment LAP AND SHOULDER BELT USED		Transported		Passenger Age 17

UNIT 2	Person Type DRIVER	Name (Last,First,Mi) GRIESEL, ANDREW, GABRIEL		Address (Street, City, State, Zip) 8501 THOMAS AVE S, BLOOMINGTON, MN 554311622	
	DOB 8/15/2003	Sex M	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED	
	Transported	Alcohol Test No, Test Not Given		Alcohol Test Result	

Property Damage Information:

Agency/Organization bloomington	Property Description PEDESTRIAN CROSSING POLE	Property Type PUBLIC	Yellow Tag # BP25008828	Owned By: CITY
------------------------------------	--	-------------------------	----------------------------	-------------------

Unit one stated she was in the left turn lane facing southbound on Penn Ave S / 81st St W to go eastbound on 81st St W.

Unit one stated she had a yellow light and began to turn as she saw unit two traveling northbound on Penn Ave S.

As Unit one pulled in front of Unit two, the crash occurred.

Unit two stated he was traveling northbound on Penn Ave S, approaching 81st St W, as Unit one pulled in front of him. This caused him to try to turn right to avoid the crash.

Unit one hit Unit two, causing the vehicle to hit the pedestrian crossing pole.

Unit one was cited for failing to yield.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency	Officer Name	Case Number	Date of Crash	Time
BLOOMINGTON POLICE DEPT	THUL, STEVEN	25008839	09/25/2025	01:00 ☒ AM ☐ PM
Road of Occurrence	City	County		
E 83RD ST	Bloomington	HENNEPIN		

UNIT 1	Person Type DRIVER		Name (Last,First,Mi) CHISLUM, ALEXANDREA, ASHLEY REENEE		Address (Street, City, State, Zip) 9100 OLD CEDAR AVE S APT 205, BLOOMINGTON, MN 554252339	
	DOB 1/25/1990		Sex F		Injury NO APPARENT INJURY	
					Safety Equipment UNKNOWN	
	Transported		Alcohol Test Unknown		Alcohol Test Result	
	Passenger Name		Passenger Injury NO APPARENT INJURY		Passenger DOB	
Passenger Safety Equipment UNKNOWN		Transported		Passenger Age		

UNIT 2	Person Type	Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DOB	Sex	Injury		Safety Equipment
			NO APPARENT INJURY		
	Transported	Alcohol Test		Alcohol Test Result	

Vehicle 2 parked on westbound 83rd Street E. just west of 5th Avenue S. Vehicle 2 rear ended vehicle 1 as it was parked and pushed it several feet along the curb. Vehicle 1 then left the scene but left a license plate behind. Owner 2 heard the crash around 1300 hours on 09/25/2025. Hit and run report completed and KOPS alert issued on the suspect vehicle.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency	Officer Name	Case Number	Date of Crash	Time
BLOOMINGTON POLICE DEPT	PATROL SEVERSON, TODD	25008849	09/25/2025	03:53 ☐ AM ☒ PM
Road of Occurrence	City	County		
At the Intersection of OLD SHAKOPEE ROAD WEST And KELL AVENUE SOUTH	Bloomington	HENNEPIN		

UNIT 1	Person Type		Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER		THOMPSON, DEANNA, SAHRA		2196 FULHAM ST, ROSEVILLE, MN 551133815	
	DOB		Sex	Injury		Safety Equipment
	9/8/1997		F	SUSPECTED MINOR INJURY (B)		LAP AND SHOULDER BELT USED
Transported			Alcohol Test		Alcohol Test Result	
Not Transported			No, Test Not Given			

UNIT 2	Person Type		Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER		BOERBOOM, SAMUEL, JAMES		11120 THOMAS AVE S, MINNEAPOLIS, MN 554313917	
	DOB		Sex	Injury	Safety Equipment	
	9/26/2007		M	NO APPARENT INJURY	LAP AND SHOULDER BELT USED	
Transported			Alcohol Test		Alcohol Test Result	
			No, Test Not Given			

Property Damage Information:

Property Owner Name MACKEY, SHAWN	Property Description DAMAGED YARD	Property Type PRIVATE	DOB 6/26/1961	Sex M
---	---	---------------------------------	-------------------------	-----------------

Witness Information:

Name	Sex
LEMBECK II, NICHOLAS ROMAN	M
Name	Sex
VEDO, JOSHUA DAVID	M

Vehicle #1 was stopped for the stop sign northbound Kell Avenue on the south side of the intersection with West Old Shakopee Road (OSR).

Vehicle #2 was westbound West Old Shakopee Road in the curb lane towards the intersection with Kell Avenue South.

Traffic was heavy on OSR and the eastbound traffic was stopped in both lanes.

Driver of vehicle #1 started to proceed north across OSR on Kell Avenue South.

Driver of vehicle #1 believed traffic was stopped both directions and thought she could cross OSR to continue north on Kell Avenue.

Driver of vehicle #1 was hit by driver of vehicle #2 as he was westbound on OSR.

Driver of vehicle #2 did not have any stop signs at this intersection.

Fault is that of vehicle #1 for failure to yield to westbound OSR traffic.

Nicholas Lembeck did not see the accident, but provided home video of the accident, which shows the above.

Witness Josh Vedo was in his car travelling west on OSR and was in the left lane next to driver of vehicle #2.

He advised the same as above.

He stated eastbound OSR was completely stopped and vehicle crossed Kell from the south side of OSR to the north Side of OSR, striking vehicle #2.

Driver of #1 was bleeding from the head and had scratches on her leg. She was seen by Allina, but declined transport. Run #252729822. She will go in on her own.

Photos and video downloaded.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name PATROL HAYES, CHAD	Case Number BP25008881	Date of Crash 09/26/2025	Time 02:31 ☐ AM ☒ PM
Road of Occurrence At the Intersection of W OLD SHAKOPEE RD And UPTON AVE			City Bloomington	County HENNEPIN

UNIT 1	Person Type		Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER		NELSON, ROCHELLE, LEE		2705 W OLD SHAKOPEE RD, BLOOMINGTON, MN 554313359	
	DOB		Sex	Injury		Safety Equipment
	12/7/1989		F	NO APPARENT INJURY		LAP AND SHOULDER BELT USED
Transported		Alcohol Test		Alcohol Test Result		
		No, Test Not Given				

UNIT 2	Person Type		Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER		JONES, STEVEN, MARK		1728 COUNTRYSIDE DR, SHAKOPEE, MN 553794616	
	DOB		Sex	Injury	Safety Equipment	
	10/31/1959		M	NO APPARENT INJURY	LAP AND SHOULDER BELT USED	
Transported			Alcohol Test		Alcohol Test Result	
			No, Test Not Given			

Witness Information:

Name	Sex
WASKO, PAUL DOUGLAS	M

- Vehicle #1 was westbound on Old Shakopee Rd.
- Vehicle #2 was eastbound in the right lane.
- A large truck was eastbound in the left lane attempting to turn left (north).
- Vehicle #1 was attempting to turn left (south) into a residential driveway.
- Due to the large truck, vehicle #1 did not see vehicle #2 traveling in the right eastbound lane.
- Vehicle #1 proceeded to turn and was struck by vehicle #2.
- Both vehicles were heavily damaged and needed to be towed.
- Both driver's declined injuries.
- End of report.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name NYBECK, MATTHEW	Case Number 25008883	Date of Crash 09/26/2025	Time 03:00 ☐ AM ☒ PM
Road of Occurrence -- NOT ON ROADWAY --			City Bloomington	County HENNEPIN

UNIT 1	Person Type	Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER	BELBACHIR, MOHAMED, ILIES		120 THOMPSON AVE W APT 309, SAINT PAUL, MN 551183148	
	DOB	Sex	Injury	Safety Equipment	
	7/24/1993	M	NO APPARENT INJURY	LAP AND SHOULDER BELT USED	
Transported		Alcohol Test		Alcohol Test Result	
		No, Test Not Given			

UNIT 2	Person Type		Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER		KITTS, STEPHEN, MARTIN		18765 ESSENCE TRL, FARMINGTON, MN 550248645	
	DOB		Sex	Injury	Safety Equipment	
	3/8/1967		M	NO APPARENT INJURY	LAP AND SHOULDER BELT USED	
Transported			Alcohol Test		Alcohol Test Result	
			No, Test Not Given			

Witness Information:

Name	Sex
MUSTAFA, GHANI MAZEN	M

Two vehicle accident in the parking lot of the strip mall for Leeann Chin (9727 Lyndale Ave S). Neither driver was injured. Neither vehicle was towed. The rear, passenger side of veh #1 struck the passenger side of veh #2.

Driver #1 stated: He was going to back out of a parking spot. He thought the other vehicle (veh #2) had passed. He then backed up and struck veh #2.

Driver #2 stated: He was driving e/b through the parking lot when he was struck by veh #1, which was backing out of a parking spot.

Witness (Ghani) stated: He was in Subway. He observed the vehicle (veh #2) traveling e/b through the lot. He saw the vehicle (veh #2) stop. The van (veh #1) then backed into the other vehicle (veh #2).

No further information.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency	Officer Name	Case Number	Date of Crash	Time
BLOOMINGTON POLICE DEPT	BROADHEAD, BAILEY	BP25008898	09/27/2025	09:29 ☒ AM ☐ PM
Road of Occurrence	City	County		
At the Intersection of FREMONT AVE S And 89TH ST W	Bloomington	HENNEPIN		

UNIT 1	Person Type	Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER	HORNADAY, JOHN, SHANNON		10824 RIVER TERRACE, BLOOMINGTON, MN 554314200	
	DOB	Sex	Injury	Safety Equipment	
	3/4/1976	M	NO APPARENT INJURY	LAP AND SHOULDER BELT USED	
Transported	Alcohol Test		Alcohol Test Result		
	No, Test Not Given				

UNIT 2	Person Type DRIVER		Name (Last,First,Mi) OGAMBA, DENNIS, OGOTI		Address (Street, City, State, Zip) 32 E 129TH ST, BURNSVILLE, MN 553373505	
	DOB 12/27/1979		Sex M		Injury NO APPARENT INJURY	
					Safety Equipment LAP AND SHOULDER BELT USED	
	Transported		Alcohol Test No, Test Not Given		Alcohol Test Result	
Passenger Name BASS, MICHAEL, ANTHONY			Passenger Injury NO APPARENT INJURY			Passenger DOB 8/31/1957
Passenger Safety Equipment LAP AND SHOULDER BELT USED			Transported			Passenger Age 68

Veh 1 was traveling eastbound on 89th St W. Veh 2 was traveling southbound on Fremont Ave S. There are no stop signs posted in either direction at this intersection.

Veh 1 and Veh 2 approached the intersection at the same time. Veh 1 failed to yield right-of-way to Veh 2. Veh 1 pulled into the intersection in front of Veh 2. Veh 2 did not have time to stop and struck Veh 1.

There was minor damage to Veh 2's front bumper including a crack to the passenger's side front bumper. Damages also included scratches and paint transfer, as well as a ripped off front license plate.

Veh 1 had moderate disabling damage to the rear driver's side tire wheel well. The top portion of the tire appeared to be bent inwards towards the vehicle, causing disabling damage. The skirting inside the wheel well was also broken, causing it to hang down onto the tire. There was also a scratched/cracked rim on the tire.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name OFFICER BUNNELL, JOHN	Case Number BP25008968	Date of Crash 09/28/2025	Time 10:20 ☐ AM ☒ PM
Road of Occurrence W 78TH ST			City Bloomington	County HENNEPIN

UNIT 1	Person Type		Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER		RODRIGUEZ TEPOZTECO, JOSE, LUIS		7213 STEVENS AVE, RICHFIELD, MN 554233128	
	DOB		Sex	Injury		Safety Equipment
	8/26/2000		M	POSSIBLE INJURY (C)		UNKNOWN
	Transported		Alcohol Test		Alcohol Test Result	
Not Transported		No, Test Not Given				
Passenger Name				Passenger Injury		Passenger DOB
DAMASO GONZALEZ, ABUNDIO				POSSIBLE INJURY (C)		4/11/1976
Passenger Safety Equipment				Transported		Passenger Age
LAP AND SHOULDER BELT USED				Not Transported		49

UNIT 2	Person Type		Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER		FUENTES, NAOMI, RAE		509 12TH AVE NE, LONSDALE, MN 550462205	
	DOB		Sex	Injury	Safety Equipment	
	4/19/2002		F	NO APPARENT INJURY	LAP AND SHOULDER BELT USED	
Transported			Alcohol Test		Alcohol Test Result	
			No, Test Not Given			

On 9/28/2025 at 2224 hours Officers were called to a PD crash at 78th St E / Nicollet Ave S.

Upon arrival, MN LIC LKE715 (unit 1) was in the left hand northbound lane on Nicollet Ave facing north with front end damage.

MN LIC MLN271 (unit 2) was partially in the left hand facing south, appearing as if they were turning left to go east on 78th St E. Unit 2 had damage to the front passenger side.

Driver of unit 2 stated she had been driving south and making a left turn onto 78th St E, when unit 1 came northbound at a very high rate of speed and struck her front passenger side.

Driver of unit 1 appeared dazed from the crash, and could not give an explanation of what occurred. Both the driver and passenger of unit 1 were evaluated on scene by Allina paramedics for minor possible injuries. Both refused transport at that time. The driver complained of chest, left shoulder, and knee pain, and the passenger complained of chest pain.

Driver of unit 1 was cited for no MN DL and driving without carrying proof of insurance.

Both vehicles were towed from scene to Chief's towing.

few pictures were able to be taken due to the arrival of the tow trucks as the injured parties were being evaluated. See diagram for vehicle locations as Officer arrived on scene.