

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name OFFICER LOUGHREY, JACK	Case Number BP25009217	Date of Crash 10/06/2025	Time 03:49 ☐ AM ☒ PM
Road of Occurrence AMERICAN BLVD W 100 FEET East From Its Intersection With AMERICAN BLVD		City Bloomington	County HENNEPIN	

UNIT 1	Person Type DRIVER		Name (Last,First,Mi) SNYDER, ANDREW, ROBERT		Address (Street, City, State, Zip) 651 AMERICAN BLVD E APT 2, BLOOMINGTON, MN 554201371	
	DOB 7/19/1962		Sex M		Injury NO APPARENT INJURY	
					Safety Equipment UNKNOWN	
	Transported		Alcohol Test No, Test Not Given		Alcohol Test Result	
Passenger Name LAGER, ERIC, MATTHEW			Passenger Injury NO APPARENT INJURY			Passenger DOB 5/27/1987
Passenger Safety Equipment LAP AND SHOULDER BELT USED			Transported			Passenger Age 38

UNIT 2	Person Type	Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER	HOGAN, IVAN, GERALD		10454 COLORADO CIR, BLOOMINGTON, MN 554381838	
	DOB	Sex	Injury		Safety Equipment
	11/21/2002	M	POSSIBLE INJURY (C)		UNKNOWN
Transported	Alcohol Test		Alcohol Test Result		
EMS Ground	No, Test Not Given				

UNIT 3	Person Type		Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER		STEARNS, JEAN, ANN		8109 XERXES CIR, BLOOMINGTON, MN 554313800	
	DOB		Sex	Injury	Safety Equipment	
	10/23/1942		F	NO APPARENT INJURY	LAP AND SHOULDER BELT USED	
Transported		Alcohol Test		Alcohol Test Result		
		No, Test Not Given				

UNIT 1 LEN108.
UNIT 2 HFS323.
UNIT 3 PTU361.

ALL THREE VEHICLES WB AMERICAN BLVD APPROACHING LYNDAL AVE S. TRAFFIC AHEAD OF UNIT 1 WHICH CAUSED UNIT 1 TO BRAKE QUICKLY. UNIT TWO WAS UNABLE TO STOP IN TIME WHICH CAUSED THE INITIAL CRASH WHICH WAS UNIT 2 REAR ENDING UNIT 1. UNIT 3 THEN WAS ALSO UNABLE TO STOP IN TIME CAUSING UNIT 3 TO REAR END UNIT 2.

Bloomington Police Dept Incident Report
Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name OFFICER DAVERN, SAMUEL	Case Number BP25009223	Date of Crash 10/06/2025	Time 06:55 ☐ AM ☒ PM
Road of Occurrence FRANCE AVE S		City Bloomington	County HENNEPIN	

UNIT 1	Person Type		Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER		MUHUMED, ABAS, ABDIFATAH		2000 PORTLAND AVE, MINNEAPOLIS, MN 554042653	
	DOB		Sex	Injury	Safety Equipment	
	4/7/2002		M	NO APPARENT INJURY	UNKNOWN	
Transported			Alcohol Test		Alcohol Test Result	
			No, Test Not Given			

UNIT 2

Person Type	Name (Last,First,Mi)		Address (Street, City, State, Zip)	
DRIVER	AMIN, RAMADAN, ABDI		1551 E 80TH ST APT 11, BLOOMINGTON, MN 554251161	
DOB	Sex	Injury	Safety Equipment	
2/4/1986	M	NO APPARENT INJURY	UNKNOWN	
Transported	Alcohol Test		Alcohol Test Result	
	No, Test Not Given			
Passenger Name		Passenger Injury		Passenger DOB
RUNSTON, MEADOW, LEE		NO APPARENT INJURY		5/24/2001
Passenger Safety Equipment		Transported		Passenger Age
UNKNOWN				24

UNIT 3	Person Type		Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER		VAN ESSEN, MARGARET, ALICE		3341 TUXEDO BLVD, MOUND, MN 553649243	
	DOB		Sex	Injury		Safety Equipment
	7/14/1989		F	NO APPARENT INJURY		UNKNOWN
Transported		Alcohol Test			Alcohol Test Result	
		No. Test Not Given				

U1 stated he was driving SB France over 494 - He saw a doordash order and looked at his phone when he rear ended U3. No injuries and veh. was towed.

U2 stated he was stopped at the light when he was rear ended by U3. U2 did not see anything jsut felt it.

U3 stated she saw U1 about to collide with her but had no where to safely move.

No injuries reported

Bloomington Police Dept Incident Report
Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name WALTON, DANIEL	Case Number 25009229	Date of Crash 10/06/2025	Time 09:10 ☐ AM ☒ PM
Road of Occurrence W 94TH ST		City Bloomington	County HENNEPIN	

UNIT 1	Person Type		Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER		BREWER, JALISSA, ALIAH		1801 PENN AV N, MINNEAPOLIS, MN 554113057	
	DOB		Sex	Injury		Safety Equipment
	6/17/2000		F	NO APPARENT INJURY		LAP AND SHOULDER BELT USED
Transported		Alcohol Test		Alcohol Test Result		
		Yes, Test Given		.11 BAC		

Property Damage Information:

Property Owner Name HOLIDAY INN AIRPORT	Property Description CHAIN LINK FENCE	Property Type PRIVATE		
---	---	---------------------------------	--	--

Unit 1 was exiting from southbound 35W to travel westbound on 94th Street West. Unit 1 was not able to negotiate the right turn and drove off the roadway on the southwest corner of the intersection. Unit 1 hit a fence which was owned by the Holiday Inn Airport at 1201 94th Street West. There were no injuries involved, however the driver of Unit 1, Brewer was arrested for 4th Degree DWI. Unit 1 was towed due to the DWI arrest.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name PATROL HAYES, CHAD	Case Number BP25009234	Date of Crash 10/07/2025	Time 07:51 ☒ AM ☐ PM
Road of Occurrence W 102ND ST 100 FEET East From Its Intersection With DREW AVE		City Bloomington	County HENNEPIN	

UNIT 1	Person Type	Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER				
	DOB	Sex	Injury		Safety Equipment
	99	NO APPARENT INJURY		LAP AND SHOULDER BELT USED	
Transported	Alcohol Test		Alcohol Test Result		
	No, Test Not Given				

Property Damage Information:

Property Owner Name LARSON, RACHEL	Property Description MAILBOX	Property Type PRIVATE	DOB 6/2/1981	Sex F
--	--	---------------------------------	------------------------	-----------------

- Vehicle west bound on 102nd St approaching Drew Ave.
- Driver claims that the steering "locked up" causing him to veer off the roadway.
- Vehicle glanced off of a light pole on the north side of 102nd St and then hit a mailbox at 3600 W 102nd St.
- Vehicle was then able to correct back on the roadway despite "locked" steering.
- Minor damage to south side of light pole and plastic mailbox was completely knocked off it's base.
- Driver did not have MN DL or permit on file and was driving himself to school.
- Driver did not call police.
- Dispatch was notified by phone that owner was in a crash.
- End of report.

Bloomington Police Dept Incident Report
Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name OFFICER CHRISTOFFERSON, NONA	Case Number BP25009249	Date of Crash 10/07/2025	Time 05:11 ☐ AM ☒ PM
Road of Occurrence E AMERICAN BLVD		City Bloomington	County HENNEPIN	

UNIT 1	Person Type DRIVER	Name (Last,First,Mi) MOHAMMADI, SHABNAM		Address (Street, City, State, Zip) 8100 31ST AVE S APT 432, BLOOMINGTON, MN 554257402	
	DOB 9/21/1990	Sex F	Injury NO APPARENT INJURY		Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given		Alcohol Test Result	

UNIT 2	Person Type DRIVER	Name (Last,First,Mi) GIZAW, ZENEBE, A		Address (Street, City, State, Zip) 5410 152ND ST W, APPLE VALLEY, MN 551246868	
	DOB 3/3/1984	Sex M	Injury NO APPARENT INJURY		Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given		Alcohol Test Result	

UNIT 3	Person Type DRIVER	Name (Last,First,Mi) JAARSO, SOLAAN, JARA		Address (Street, City, State, Zip) 4286 130TH AVE NE, BLAINE, MN 554492213	
	DOB 6/29/1988	Sex M	Injury NO APPARENT INJURY		Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given		Alcohol Test Result	

Witness Information:

Name ROHLAND, DEBBIE ANN	Sex F
-----------------------------	----------

Unit 1: Traveling West on American Blvd E / Metro drive in the right lane. Unit 3 turned left, onto Metro Dr directly in front of Unit 1. Unit 1 attempted to swerve onto the sidewalk to avoid the collision with Unit 3. Unit 3 still hit the front driver's side of Unit 1. Unit 1 flipped over an unknown number of times after being hit by Unit 3 and the curb for the sidewalk. Unit 1 stated they were traveling the speed limit and did not have any visible injuries.

Unit 2: Parked at the stop sign on Metro Dr, facing American Blvd E waiting to turn east. Unit 2 was hit by Unit 3 after Unit 3 hit Unit 1. The front driver's side and driver's door were damaged but the vehicle is operational.

Unit 3: Stated he was turning left (north) onto Metro Dr from eastbound American Blvd E. Unit 3 stated that Unit 1 was traveling too fast, so he did not see the vehicle.

Witness 1: Was parked behind Unit 2 at the stop sign and saw Unit 3 hit Unit 1, which then hit Unit 2. Witness saw Unit 1 flip over an unknown number of times.

Bloomington Police Dept Incident Report
Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name PATROL HAYES, CHAD	Case Number BP25009338	Date of Crash 10/10/2025	Time 11:55 ☒ AM ☐ PM
Road of Occurrence -- NOT ON ROADWAY --			City Bloomington	County HENNEPIN

UNIT 1	Person Type	Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER	ANDERSON, BRENT, CHARLES		961 MONROE ST, PRESCOTT, WI 54021	
	DOB	Sex	Injury	Safety Equipment	
	4/21/1964	M	NO APPARENT INJURY	LAP AND SHOULDER BELT USED	
Transported	Alcohol Test		Alcohol Test Result		
	No, Test Not Given				

UNIT 2	Person Type	Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DOB	Sex	Injury NO APPARENT INJURY		Safety Equipment
	Transported	Alcohol Test		Alcohol Test Result	

- Vehicle #1 with trailer was attempting to make a delivery a strip mall.
- Driver #1 realized that he would not be able to make the turn in the back of the business so her attempted to turn around in the parking lot.
- Vehicle #2 was legally parked and there were no occupants.
- Vehicle #1's trailer struck the front passenger corner of vehicle #2 dragging it out of it's parking stall.
- Minor scratch on the trailer and disabling damage to vehicle #2.
- MN State Trooper Cruiser was provided the information of the crash.
- A Waiver was completed and MN State Patrol did not respond to the scene.
- Vehicle #2 was not blocking so they were allowed to contact their own tow service.
- End of report.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name OFFICER MERSETH, DANIEL	Case Number 25009346	Date of Crash 10/10/2025	Time 03:30 ☐ AM ☒ PM
Road of Occurrence W OLD SHAKOPEE RD		City Bloomington	County HENNEPIN	

UNIT 1	Person Type		Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER		CLAY, MICO, DAJAUN		10482 COLORADO CIR, BLOOMINGTON, MN 554381838	
	DOB		Sex	Injury	Safety Equipment	
	1/16/2003		M	NO APPARENT INJURY	LAP AND SHOULDER BELT USED	
Transported		Alcohol Test		Alcohol Test Result		
		No, Test Not Given				

UNIT 2	Person Type		Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER		GUSTNER, CATHY, JOY		2121 W 104TH ST, BLOOMINGTON, MN 554313403	
	DOB		Sex	Injury	Safety Equipment	
	3/9/1956		F	NO APPARENT INJURY	LAP AND SHOULDER BELT USED	
Transported			Alcohol Test		Alcohol Test Result	
			No, Test Not Given			

V1 was w/b Old Shakopee Rd left lane at Sheridan Ave S. V2 was w/b Old Shakopee Rd left lane stopped waiting to make a left turn to s/b Sheridan Ave S. V1 rear ended V2.
No injuries.

Bloomington Police Dept Incident Report

Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name OFFICER BLAINE, ALEX	Case Number 25009355	Date of Crash 10/10/2025	Time 05:08 ☐ AM ☒ PM
Road of Occurrence -- NOT ON ROADWAY --		City Bloomington	County HENNEPIN	

UNIT 1	Person Type		Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER		BEINTEMA, JOHN, LEE		10531 MARYLAND CIR S, BLOOMINGTON, MN 554382130	
	DOB		Sex	Injury	Safety Equipment	
	3/15/1952		M	POSSIBLE INJURY (C)	LAP AND SHOULDER BELT USED	
Transported		Alcohol Test		Alcohol Test Result		
EMS Ground		No, Test Not Given				

UNIT 2	Person Type		Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DOB		Sex	Injury		Safety Equipment
				POSSIBLE INJURY (C)		
	Transported		Alcohol Test		Alcohol Test Result	

Officers dispatched to a crash in the US Bank parking lot. U1 had struck U2 (a parked car) and was stuck against it. D1 was slumped over with his foot still on the gas with the tires spinning.

We arrived and could not get the driver to put the car in park. We boxed the vehicle in, opened the driver's door, and turned the car off. D1 was nearly unconscious and had to be pulled from the car and laid on the ground.

Paramedics responded and found D1's blood sugar was dangerously low. There was no sign of drug or alcohol impairment. D1 was treated and transported to the hospital for his diabetic issue. D1's driver's license record noted previous paperwork for diabetes.

It was determined D1 began having a diabetic episode and lost control of the car. It struck the parked U2 and got stuck against it until police arrived.

Owner of U2 was notified.

Bloomington Police Dept Incident Report
Minnesota Statute 13.82 subdivision 6

Agency	Officer Name	Case Number	Date of Crash	Time
BLOOMINGTON POLICE DEPT	PATROL SMITH, MICHAEL	25009394	10/11/2025	06:32 ☐ AM ☒ PM
Road of Occurrence		City	County	
RAMP482		Bloomington	HENNEPIN	

UNIT 1	Person Type	Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER	KEOPHOTHISANE, VANCHAY		850 W 106TH ST APT 4, BLOOMINGTON, MN 554205608	
	DOB	Sex	Injury	Safety Equipment	
	12/15/1956	M	NO APPARENT INJURY	LAP AND SHOULDER BELT USED	
	Transported	Alcohol Test		Alcohol Test Result	
		No, Test Not Given			
	Passenger Name		Passenger Injury		Passenger DOB
	KIKHAMSOUK, VIXIAN, SIRIOUTHAY		NO APPARENT INJURY		12/2/1955
	Passenger Safety Equipment		Transported		Passenger Age
	LAP AND SHOULDER BELT USED				69

UNIT 2	Person Type	Name (Last,First,Mi)		Address (Street, City, State, Zip)	
	DRIVER	THORALDSON, TERRENCE, MARK		11405 GOODRICH CIR, BLOOMINGTON, MN 554373517	
	DOB	Sex	Injury	Safety Equipment	
	1/18/1961	M	SUSPECTED SERIOUS INJURY (A)	DOT COMPLIANT FULL FACE, FULL PROTECTIVE GEAR (MOTORCYCLE SPECIFIC JACKET, PANTS, BOOTS, AND GLOVES)	
	Transported	Alcohol Test		Alcohol Test Result	
	EMS Ground	No, Test Not Given			

Unit 1 driving westbound 106th St underneath 35W attempting to turn onto on-ramp of southbound 35W when Unit 2 was driving eastbound 106th. Both collided head-on causing severe damage to Unit 1 and causing driver of Unit 2 to fall off scooter and cause severe damage. Driver and passenger of Unit 1 did not have any visible injuries, and denied any. Driver of Unit 2 had a significant leg injury and was transported to HCMC via Allina. Driver of Unit 1 said Unit 2 did not have a headlight on at the time of the crash. There is no way of verifying whether that was true or not due to the severe damage to Unit 2.