

# Bloomington Police Dept Incident Report

## Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name PATROL MURPHY, JACOB	Case Number 26001918	Date of Crash 03/02/2026	Time 03:42 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence E BUSH LAKE RD		City Bloomington	County HENNEPIN	

<b>UNIT 1</b>	Person Type <b>DRIVER</b>	Name (Last,First,Mi) <b>KENNEDY, ROBIN, PERSON</b>	Address (Street, City, State, Zip) <b>7341 AUTUMN CHACE CIR, MINNEAPOLIS, MN 554381111</b>	
	DOB <b>3/1/1969</b>	Sex <b>M</b>	Injury <b>NO APPARENT INJURY</b>	Safety Equipment <b>LAP AND SHOULDER BELT USED</b>
	Transported	Alcohol Test <b>No, Test Not Given</b>	Alcohol Test Result	

<b>UNIT 2</b>	Person Type <b>DRIVER</b>	Name (Last,First,Mi) <b>KALTENHAUSER, JAMES, FARLEY</b>	Address (Street, City, State, Zip) <b>4809 W 110TH ST, BLOOMINGTON, MN 554373221</b>	
	DOB <b>3/2/1968</b>	Sex <b>M</b>	Injury <b>NO APPARENT INJURY</b>	Safety Equipment <b>LAP AND SHOULDER BELT USED</b>
	Transported	Alcohol Test <b>No, Test Not Given</b>	Alcohol Test Result	

Unit one was directly behind unit two, both traveling southbound on East Bush Lake Road, approaching the intersection of East Bush Lake Road and 84th street. Unit Two was turning westbound onto 84th, with Unit one following and also turning westbound onto 84th street. Unit two stopped for the railroad tracks, (as required by law for school buses) while Unit two was stopped Unit one rear ended Unit two. No injuries reported on the school bus (Unit two) or by the driver of Unit one.

# Bloomington Police Dept Incident Report

## Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name OFFICER BURT, ANDREW	Case Number BP26001924	Date of Crash 03/02/2026	Time 08:00 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence At the Intersection of PENN AVE S And W 98TH ST		City Bloomington	County HENNEPIN	

<b>UNIT 1</b>	Person Type DRIVER	Name (Last,First,Mi) MASON, DENISE, MARIE	Address (Street, City, State, Zip) 1701 W BURNSVILLE PKWY APT 307, BURNSVILLE, MN 553372453	
	DOB 11/12/1972	Sex F	Injury POSSIBLE INJURY (C)	Safety Equipment LAP AND SHOULDER BELT USED
	Transported EMS Ground	Alcohol Test No, Test Not Given	Alcohol Test Result	

<b>UNIT 2</b>	Person Type DRIVER	Name (Last,First,Mi) MCKIGNEY, CHRISTINE, MARI OBENLAND	Address (Street, City, State, Zip) 5121 18TH AVE S, MINNEAPOLIS, MN 554171221	
	DOB 7/10/1977	Sex F	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

Unit 1 and Unit 2 were both stopped at a red light on Penn Ave S facing southbound. Unit 2 driver stated she started a new job with Target Delivery. Unit 2 driver said she reached down to look at her phone. Unit 2 driver said she thinks she thought she saw the light turn green and took her foot off the brake. Unit 2 said her vehicle then rolled into Unit 1. Unit 2 driver said she did not accelerate at all. Both drivers were wearing their seat belts and neither vehicle had airbag deployment.

Unit 1 driver complained of head pain. Unit 1 driver was concerned due to prior injuries and was transported by Allina Ambulance.

Chief's Towing towed the vehicle due to the vehicle blocking and Unit 1 driver was transported.

# Bloomington Police Dept Incident Report

## Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name OFFICER MULVIHILL, TRISTEN	Case Number BP26001957	Date of Crash 03/03/2026	Time 07:45 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence At the Intersection of PENN AVE S And 82ND ST W		City Bloomington	County HENNEPIN	

<b>UNIT 1</b>	Person Type DRIVER	Name (Last,First,Mi) JOHNSON, JANA, JON	Address (Street, City, State, Zip) 11618 RODEO DR, BURNSVILLE, MN 553371289	
	DOB 1/15/1956	Sex F	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

<b>UNIT 2</b>	Person Type DRIVER	Name (Last,First,Mi) OBST, CAROLINE, ANN	Address (Street, City, State, Zip) 3330 EDINBOROUGH WAY APT 1003, MINNEAPOLIS, MN 55435	
	DOB 3/23/1947	Sex F	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

### Witness Information:

Name NELSON, KARL VIRL	Sex M
---------------------------	----------

Unit one stated she began turning left from southbound Penn Ave onto eastbound 82nd, unsure of the light's color. She believed she was traveling 5-10 mph. She did not see any northbound vehicles on Penn Ave before her vehicle was struck.

Unit two stated she was traveling northbound on Penn Ave, approaching 82nd, when Unit one began turning in front of her. At that moment, Unit two stated she had a green light, applied her brakes, but was unable to stop in time and collided with Unit one.

Witness stated he was right behind Unit one, traveling South on Penn in the turn lane. He stated they had the flashing yellow yield light at the Eastbound 82nd turn. He stated that Unit Two was traveling North on Penn. As Unit One completed her left turn, Unit Two collided with her on the passenger side, resulting in Unit One rolling over. The witness stated that he thought Unit two was traveling at a reasonable speed, not speeding. The witness thought that maybe Unit one didn't see Unit two when Unit two entered the intersection.

# Bloomington Police Dept Incident Report

## Minnesota Statute 13.82 subdivision 6

Agency BLOOMINGTON POLICE DEPT	Officer Name HYDEEN, BRAD	Case Number BP26002037	Date of Crash 03/06/2026	Time 01:49 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM
Road of Occurrence PORTLAND AVE S		City Bloomington	County HENNEPIN	

<b>UNIT 1</b>	Person Type DRIVER	Name (Last,First,Mi) BOE, BRODEN, DEAN	Address (Street, City, State, Zip) 2015 CENTRAL AVE NE APT 101, MINNEAPOLIS, MN 554184518	
	DOB 4/11/2000	Sex M	Injury NO APPARENT INJURY	Safety Equipment LAP AND SHOULDER BELT USED
	Transported	Alcohol Test No, Test Not Given	Alcohol Test Result	

<b>UNIT 2</b>	Person Type DRIVER	Name (Last,First,Mi) NIEBERGALL-GONZALEZ, PATRICIA, ANNE	Address (Street, City, State, Zip) 3548 3RD AVE S, MINNEAPOLIS, MN 554084524	
	DOB 7/24/1957	Sex F	Injury POSSIBLE INJURY (C)	Safety Equipment LAP AND SHOULDER BELT USED
	Transported EMS Ground	Alcohol Test No, Test Not Given	Alcohol Test Result	

Passenger Name FRANTZ, SAMUEL	Passenger Injury NO APPARENT INJURY	Passenger DOB 5/26/1992
Passenger Safety Equipment LAP AND SHOULDER BELT USED	Transported	Passenger Age 33
Passenger Name FORRETTE, ANDREA	Passenger Injury NO APPARENT INJURY	Passenger DOB
Passenger Safety Equipment LAP AND SHOULDER BELT USED	Transported	Passenger Age
Passenger Name MACIASEK, JEFFREY	Passenger Injury NO APPARENT INJURY	Passenger DOB 11/27/1967
Passenger Safety Equipment LAP AND SHOULDER BELT USED	Transported	Passenger Age 58

Veh 1 SB Portland crossing 78th St off ramp intersection and hit Veh 2 who was WB to NB . Veh 1 driver stated he didn't know if he had a green light or not. Veh 1 had a dash cam, unknown if it was running, denied viewing. No witness stopped. Possible injury to Veh 2 occupants. State Patrol completed inspection on Veh 1.